ALTERNATIVE COMPARISON -- Bangerter Intersection

	ALIERNATIVE			
ALTERNATIVE	Transportation Supportive Criteria	Community Supportive Criteria	Environmental Supportive Criteria	Potentially Forwarded
No Action				
At-grade Improve- ments				
Single Point Urban Interchange Bangerter Over				
Single Point Urban Interchange 3500 South Over				
Through Lanes Over 3500 South Interchange				
High Volume Intersection (CFI)				
3500 South Depressed at Bangerter Interchange				
Area Needs	 Improve walk-ability along 3500 South Improve cross-ability at key pedestrian crossings Increase opportunity for north-south pedestrian crossings Improve transit facilities (stops, etc.) Improve transit services within corridor Address current and projected congestion Improve intersection conditions (3200 W & 3600 W) Improve mid-block safety Address anticipated safety problems at intersections 	 Improve walk-ability along 3500 South Improve cross-ability at key pedestrian crossings Improve mid-block safety Be consistent with the downtown character Provide improved, consistent street lighting along 3500 S. Promote downtown business environment Address drainage problems Accommodate transit supportive land use 	environmental impacts • Ability to implement	DOES NOT meet needs PARTIALLY meets needs MOSTLY meets needs DOES meet needs
	Address mobility for all modes Ability to implement	 Public acceptance Ability to implement 		

